




SERVICE BULLETIN	
Product:	French Door Refrigerators
Bulletin Date:	03/19/2015
Bulletin Number	ASC20150319001
Models:	RF23HCEDB/ RF23HCEDT/ RF23HSES/ RF23HTEDB / RF24FSEDB/ RF28HDEDB/ RF28HDEDT/ RF28HFEDB/ RF28HFEDT/ RF28HMEDB/ RF28HMELB/ RF30HBED/ RF30HDEDT/ RF31FMEDB / RF31FMESB/ RF323TEDB / All Colors

SUBJECT: Door Alignment Screw Change


Information Only

- The Allen bolt located in the right middle hinge is being replaced by a Phillips head bolt.
- All new units, beginning with March 2015 production, will have the Phillips head bolt.
- All right door adjustments can now be made using a Phillips head screwdriver.
- The Allen tool will no longer be supplied with the unit.
- The user manual will be updated to reflect the change.

Old Allen Bolt - 6011-001442




New Phillips Head Bolt - DA66-00688A



Allen tool no longer supplied.



Location of Phillips Head Bolt



Note: Consult the Samsung Service Website at <http://.service.samsungportal.com> for the Service Manual and other information on this product.

Symptom Codes

Symptom 1	Symptom 2	Symptom 3	Symptom 4
2	02	01	

This information is published for informational purposes only and intended for use only by personnel qualified for the specific tasks depicted. Qualified personnel are those who, based on their training and experience, are capable of identifying risks and avoiding potential hazards when handling or servicing a product. Only qualified personnel should repair products powered by electricity. Any attempt to handle, service or repair the product or products by anyone other than qualified personnel could result in serious injury or death. You agree that your use of and reliance on this information is at your sole risk. This information is subject to change or update without notice. There are no warranties, either expressed or implied, regarding the accuracy or completeness of this information.