

SERVICE BULLETIN CREF20070202
LG Electronics Monterrey México

Approval table with columns: Service, R&D Engineer, R&D Leader, R&D Mgr, R&D Director

Code: SB-07-011
Date of Issue: Mar 27, 2007

Factory Model: Refer to page 3
Buyer Model: Refer to page 3
Buyer Name: Refer to page 3 Effective Date: Mar 23, 2007
Serial Number: 703MR*****
Subject: Compressor Damper standardization
Total pages including cover (qty): 3

Table with 8 columns: No, LOC No., BEFORE CHANGE (PART No., DESC/SPEC), AFTER CHANGE (PART No., DESC/SPEC), Code, REMARK. Contains 5 rows of data.

Reason of change:
Standardization of compressor damper.

Table with 3 main sections: Alphabetic Code (A, B, C, D), Numeric Code (1-7), and Agreement (SVC, QA, MAT). Includes diagrams for part usage scenarios.


SERVICE BULLETIN

LG Electronics Monterrey México

Code: SB-07-011

Date of Issue: Mar 27, 2007

● Exploded View from Service Manual



● Picture

BEFORE



5040JA3071A

AFTER



5040JA3073A

SERVICE BULLETIN

LG Electronics Monterrey México

Code: SB-07-011

Date of Issue: Mar 27, 2007

● **Models affected by this bulletin:**

Product Model	Product Suffix	Buyer Code	Buyer Name	Sales Model	Sales Suffix
GM-L267BNRY	ANTCLGA	US000001	LGEUS	LSC26905TT	ANTCLGA
GM-L267BNRY	ANTCMXM	MX000001	LGEMS	GM-L261BNRY	ANTCMXM
GM-L267BQRY	ASWCLGA	US000001	LGEUS	LSC26905SW	ASWCLGA
GM-L267BQRY	ASWCMXM	MX000001	LGEMS	GM-L265BQRY	ASWCMXM
GM-L267BQRY	AWBCLGA	US000001	LGEUS	LSC26905SB	AWBCLGA