

Title	HC2 Error Display		
Service Bulletin Number	ASC20170502001	Models Involved	Dryers DVG60M9900** DVG55M9600**
Create Date	April 20, 2017		
Revision Date	NA		

Symptom

HC2 displays during operation. Appears only on gas models

Solution

To resolve this issue, **replace the Main PCB**. (DC92-01729L)



Parts Name	Affected Date Range	How to check a date
Assy PCB EEPROM	January through March, 2017. In the Serial Number: J (2017) in the 8th place and 1, 2, or 3 in the 9th place.	

Affected Models / Part Information

PRODUCT	MODEL	Affective Serial No Range	SVC PARTS CODE	SVC PARTS NAME
GAS DRYER	DVG60M9900V/A3	0ASV5BAJ200005M~0ASV5BAJ300754L	DC92-01729L	ASSY MAIN PBA (Lower)
	DVG60M9900W/A3	0ASR5BAJ200073T~0ASR5BAJ300189P		
	DVG55M9600V/A3	0ASU5BAJ200003T~0ASU5BAJ300384F		
	DVG55M9600W/A3	0ASQ5BAJ200001K~0ASQ5BAJ300151Y		

How to check production dates by serial number

Digit	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
(Ex)	0	A	S	V	5	B	A	J	2	1	2	3	4	5	A

CODE	YEAR
D	2013
F	2014
G	2015
H	2016
J	2017

CODE	MONTH
1	Jan
2	Feb
3	Mar
4	Apr
5	May
6	Jun
7	Jul
8	Aug
9	Sep
A	Oct
B	Nov
C	Dec

This information is published for experienced repair technicians only and is not intended for use by the public. It does not contain warnings to advise non-technical individuals of possible dangers in attempting to service a product. Only experienced professional technicians should repair products powered by electricity. Any attempt to service or repair the product or products dealt with in this information by anyone else could result in serious injury or death. Information provided in this bulletin is subject to change or update without notice.