



SUBJECT: Parts Change

Starting with July Production, the interior lighting for the model listed above has been changed from incandescent lighting to LED lighting. The new parts are NOT interchangeable with the old parts. Please refer to the graphic to determine what month the product was produced.

NOTE: Please review all five pages of this bulletin to see all the parts involved.



SERVICE BULLETIN	
PRODUCT:	Refrigerator
BULLETIN NUMBER:	ASC20100714001
BULLETIN DATE:	07/14/2010
MODELS:	RF266AZBP/XAA ,RF266AZPN/XAA ,RF266AZRS/XAA, RF266AZWP/XAA, RF267AZBP/XAA ,RF267AZPN/XAA RF267AZRS/XAA, RF267AZWP/XAA, RF268ABBP/XAA, RF268ABPN/XAA, RF268ABRS/XAA, RF268ABWP/XAA RF26XAZBP/XAA, RF26XAZRS/XAA, RF26XAZWP/XAA, RFG295ABBP/XAA, RFG295ABPN/XAA, RFG295ABRS/XAA RFG295ABWP/XAA,RFG297ABBP/XAA, RFG297ABPN/XAA, RFG297ABRS/XAA, RFG297ABWP/XAA, RFG298AABP/XAA RFG298AAPN/XAA, RFG298AARS/XAA, RFG298AAWP/XAA, RFG299ABRS/XAA

C998 – Production Information 4 = Refrigerator 1 = Factory Location A = Production Line Z = Production year (Z = 2010) 2 = Production Month (1 = Jan, 2 = Feb, 6 = June, A = Oct, B= Nov, C= Dec) 00050 = Unit Serial Number X = Check Digit	 4 1 A Z 2 00050 Lot Number Month - Feb Year 2010 Product Line Factory C99841AZ200050 X
---	---

This information is published for experienced repair technicians only and is not intended for use by the public. It does not contain warnings to advise non-technical individuals of possible dangers in attempting to service a product. Only experienced professional technicians should repair products powered by electricity. Any attempt to service or repair the product or products dealt with in this information by anyone else could result in serious injury or death. Information provided in this bulletin is subject to change or update without notice.

Description	ASSY PCB MAIN		COVER-LAMP FRE	
Image				
Model	Old Part	New Part	Old Part	New Part
RF266AZBP/XAA	DA41-00689A	DA41-00689G	DA63-04296A	DA63-04955A
RF266AZPN/XAA	DA41-00689A	DA41-00689G	DA63-04296A	DA63-04955A
RF266AZRS/XAA	DA41-00689A	DA41-00689G	DA63-04296A	DA63-04955A
RF266AZWP/XAA	DA41-00689A	DA41-00689G	DA63-04296A	DA63-04955A
RF267AZBP/XAA	DA41-00689D	DA41-00689K	DA63-04296A	DA63-04955A
RF267AZPN/XAA	DA41-00689D	DA41-00689K	DA63-04296A	DA63-04955A
RF267AZRS/XAA	DA41-00689D	DA41-00689K	DA63-04296A	DA63-04955A
RF267AZWP/XAA	DA41-00689D	DA41-00689K	DA63-04296A	DA63-04955A
RF268ABBP/XAA	DA41-00620A	DA41-00620C	DA63-03420A	DA63-04955A
RF268ABPN/XAA	DA41-00620A	DA41-00620C	DA63-03420A	DA63-04955A
RF268ABRS/XAA	DA41-00620A	DA41-00620C	DA63-03420A	DA63-04955A
RF268ABWP/XAA	DA41-00620A	DA41-00620C	DA63-03420A	DA63-04955A
RF26XAZBP/XAA	DA41-00689E	DA41-00689L	DA63-04296A	DA63-04955A
RF26XAZRS/XAA	DA41-00689E	DA41-00689L	DA63-04296A	DA63-04955A
RF26XAZWP/XAA	DA41-00689E	DA41-00689L	DA63-04296A	DA63-04955A
RFG295ABBP/XAA	DA41-00538H	DA41-00538N	DA63-04296A	DA63-04955A
RFG295ABPN/XAA	DA41-00538H	DA41-00538N	DA63-04296A	DA63-04955A
RFG295ABRS/XAA	DA41-00538H	DA41-00538N	DA63-04296A	DA63-04955A
RFG295ABWP/XAA	DA41-00538H	DA41-00538N	DA63-04296A	DA63-04955A
RFG297ABBP/XAA	DA41-00538G	DA41-00538M	DA63-04296A	DA63-04955A
RFG297ABPN/XAA	DA41-00538G	DA41-00538M	DA63-04296A	DA63-04955A
RFG297ABRS/XAA	DA41-00538G	DA41-00538M	DA63-04296A	DA63-04955A
RFG297ABWP/XAA	DA41-00538G	DA41-00538M	DA63-04296A	DA63-04955A
RFG298AABP/XAA	DA41-00620B	DA41-00620D	DA63-04296A	DA63-04955A
RFG298AAPN/XAA	DA41-00620B	DA41-00620D	DA63-04296A	DA63-04955A
RFG298AARS/XAA	DA41-00620B	DA41-00620D	DA63-04296A	DA63-04955A
RFG298AAWP/XAA	DA41-00620B	DA41-00620D	DA63-04296A	DA63-04955A
RFG299ABRS/XAA	DA41-00538J	DA41-00538P	DA63-04296A	DA63-04955A

This information is published for experienced repair technicians only and is not intended for use by the public. It does not contain warnings to advise non-technical individuals of possible dangers in attempting to service a product. Only experienced professional technicians should repair products powered by electricity. Any attempt to service or repair the product or products dealt with in this information by anyone else could result in serious injury or death. Information provided in this bulletin is subject to change or update without notice.

Description	ASSY-LAMP LED FRE		COVER LAMP-REF	
Image				
Model	Old Part	New Part	Old Part	New Part
RF266AZBP/XAA	4713-001223	DA96-00398G	DA63-05264A	DA63-05600A
RF266AZPN/XAA	4713-001223	DA96-00398G	DA63-05264A	DA63-05600A
RF266AZRS/XAA	4713-001223	DA96-00398G	DA63-05264A	DA63-05600A
RF266AZWP/XAA	4713-001223	DA96-00398G	DA63-05264A	DA63-05600A
RF267AZBP/XAA	4713-001223	DA96-00398G	DA63-05264A	DA63-05600A
RF267AZPN/XAA	4713-001223	DA96-00398G	DA63-05264A	DA63-05600A
RF267AZRS/XAA	4713-001223	DA96-00398G	DA63-05264A	DA63-05600A
RF267AZWP/XAA	4713-001223	DA96-00398G	DA63-05264A	DA63-05600A
RF268ABBP/XAA	4713-001223	DA96-00398G	DA63-03738A	DA63-05600A
RF268ABPN/XAA	4713-001223	DA96-00398G	DA63-03738A	DA63-05600A
RF268ABRS/XAA	4713-001223	DA96-00398G	DA63-03738A	DA63-05600A
RF268ABWP/XAA	4713-001223	DA96-00398G	DA63-03738A	DA63-05600A
RF26XAZBP/XAA	4713-001223	DA96-00398G	DA63-05264A	DA63-05600A
RF26XAZRS/XAA	4713-001223	DA96-00398G	DA63-05264A	DA63-05600A
RF26XAZWP/XAA	4713-001223	DA96-00398G	DA63-05264A	DA63-05600A
RFG295ABBP/XAA	4713-001223	DA96-00398G	DA63-04327A	DA63-05612A
RFG295ABPN/XAA	4713-001223	DA96-00398G	DA63-04327A	DA63-05612A
RFG295ABRS/XAA	4713-001223	DA96-00398G	DA63-04327A	DA63-05612A
RFG295ABWP/XAA	4713-001223	DA96-00398G	DA63-04327A	DA63-05612A
RFG297ABBP/XAA	4713-001223	DA96-00398G	DA63-04326A	DA63-05612A
RFG297ABPN/XAA	4713-001223	DA96-00398G	DA63-04326A	DA63-05612A
RFG297ABRS/XAA	4713-001223	DA96-00398G	DA63-04326A	DA63-05612A
RFG297ABWP/XAA	4713-001223	DA96-00398G	DA63-04326A	DA63-05612A
RFG298AABP/XAA	4713-001223	DA96-00398G	DA63-04326A	DA63-05612A
RFG298AAPN/XAA	4713-001223	DA96-00398G	DA63-04326A	DA63-05612A
RFG298AARS/XAA	4713-001223	DA96-00398G	DA63-04326A	DA63-05612A
RFG298AAWP/XAA	4713-001223	DA96-00398G	DA63-04326A	DA63-05612A
RFG299ABRS/XAA	4713-001223	DA96-00398G	DA63-04326A	DA63-05612A

This information is published for experienced repair technicians only and is not intended for use by the public. It does not contain warnings to advise non-technical individuals of possible dangers in attempting to service a product. Only experienced professional technicians should repair products powered by electricity. Any attempt to service or repair the product or products dealt with in this information by anyone else could result in serious injury or death. Information provided in this bulletin is subject to change or update without notice.

Description	ASSY-LAMP LED REF		ASSY COVER-SENSOR	
				
Model	Old Part	New Part	Old Part	New Part
RF266AZBP/XAA	DA96-00398B	DA96-00398J	DA97-02019B	DA97-02019A
RF266AZPN/XAA	DA96-00398B	DA96-00398J	DA97-02019B	DA97-02019A
RF266AZRS/XAA	DA96-00398B	DA96-00398J	DA97-02019B	DA97-02019A
RF266AZWP/XAA	DA96-00398B	DA96-00398J	DA97-02019B	DA97-02019A
RF267AZBP/XAA	DA96-00398B	DA96-00398J	DA97-02019B	DA97-02019A
RF267AZPN/XAA	DA96-00398B	DA96-00398J	DA97-02019B	DA97-02019A
RF267AZRS/XAA	DA96-00398B	DA96-00398J	DA97-02019B	DA97-02019A
RF267AZWP/XAA	DA96-00398B	DA96-00398J	DA97-02019B	DA97-02019A
RF268ABBP/XAA	DA96-00398B	DA96-00398J	No Change	No Change
RF268ABPN/XAA	DA96-00398B	DA96-00398J	No Change	No Change
RF268ABRS/XAA	DA96-00398B	DA96-00398J	No Change	No Change
RF268ABWP/XAA	DA96-00398B	DA96-00398J	No Change	No Change
RF26XAZBP/XAA	DA96-00398B	DA96-00398J	DA97-02019B	DA97-02019A
RF26XAZRS/XAA	DA96-00398B	DA96-00398J	DA97-02019B	DA97-02019A
RF26XAZWP/XAA	DA96-00398B	DA96-00398J	DA97-02019B	DA97-02019A
RFG295ABBP/XAA	4713-001223	DA96-00398J	No Change	No Change
RFG295ABPN/XAA	4713-001223	DA96-00398J	No Change	No Change
RFG295ABRS/XAA	4713-001223	DA96-00398J	No Change	No Change
RFG295ABWP/XAA	4713-001223	DA96-00398J	No Change	No Change
RFG297ABBP/XAA	DA96-00398A	DA96-00398J	No Change	No Change
RFG297ABPN/XAA	DA96-00398A	DA96-00398J	No Change	No Change
RFG297ABRS/XAA	DA96-00398A	DA96-00398J	No Change	No Change
RFG297ABWP/XAA	DA96-00398A	DA96-00398J	No Change	No Change
RFG298AABP/XAA	DA96-00398A	DA96-00398J	No Change	No Change
RFG298AAPN/XAA	DA96-00398A	DA96-00398J	No Change	No Change
RFG298AARS/XAA	DA96-00398A	DA96-00398J	No Change	No Change
RFG298AAWP/XAA	DA96-00398A	DA96-00398J	No Change	No Change
RFG299ABRS/XAA	DA96-00398A	DA96-00398J	No Change	No Change

This information is published for experienced repair technicians only and is not intended for use by the public. It does not contain warnings to advise non-technical individuals of possible dangers in attempting to service a product. Only experienced professional technicians should repair products powered by electricity. Any attempt to service or repair the product or products dealt with in this information by anyone else could result in serious injury or death. Information provided in this bulletin is subject to change or update without notice.

Description	SENSOR	
		
Model	Old Part	New Part
RF266AZBP/XAA	DA32-00011U	DA32-10105B
RF266AZPN/XAA	DA32-00011U	DA32-10105B
RF266AZRS/XAA	DA32-00011U	DA32-10105B
RF266AZWP/XAA	DA32-00011U	DA32-10105B
RF267AZBP/XAA	DA32-00011U	DA32-10105B
RF267AZPN/XAA	DA32-00011U	DA32-10105B
RF267AZRS/XAA	DA32-00011U	DA32-10105B
RF267AZWP/XAA	DA32-00011U	DA32-10105B
RF268ABBP/XAA	No Change	No Change
RF268ABPN/XAA	No Change	No Change
RF268ABRS/XAA	No Change	No Change
RF268ABWP/XAA	No Change	No Change
RF26XAZBP/XAA	DA32-00011U	DA32-10105B
RF26XAZRS/XAA	DA32-00011U	DA32-10105B
RF26XAZWP/XAA	DA32-00011U	DA32-10105B
RFG295ABBP/XAA	No Change	No Change
RFG295ABPN/XAA	No Change	No Change
RFG295ABRS/XAA	No Change	No Change
RFG295ABWP/XAA	No Change	No Change
RFG297ABBP/XAA	No Change	No Change
RFG297ABPN/XAA	No Change	No Change
RFG297ABRS/XAA	No Change	No Change
RFG297ABWP/XAA	No Change	No Change
RFG298AABP/XAA	No Change	No Change
RFG298AAPN/XAA	No Change	No Change
RFG298AARS/XAA	No Change	No Change
RFG298AAWP/XAA	No Change	No Change
RFG299ABRS/XAA	No Change	No Change

Note: Consult the Samsung Service Website at (<http://service.samsungportal.com>) for the Service Manual and other information on this product.

This information is published for experienced repair technicians only and is not intended for use by the public. It does not contain warnings to advise non-technical individuals of possible dangers in attempting to service a product. Only experienced professional technicians should repair products powered by electricity. Any attempt to service or repair the product or products dealt with in this information by anyone else could result in serious injury or death. Information provided in this bulletin is subject to change or update without notice.